

i-LUMINOSITY
LED LIGHTING FIXTURES

Date: _____
Project: _____
Price: _____

360 Degree Illumination Light Install Instructions



Wiring diagram



Installation Instructions

1. Fix the ceiling copper parts (A) on the ceiling, and screw the steel wires through the copper nuts (B) into the (A), then suspended them in tum;

2. The telescopic copper piece (C) is screwed into the copper nut (D) to suspended the pendant. The height of the pendant could be 8' adjusted by (C);


3. Fix the I-bracket (F) on the ceiling, and fasten the cable to the ceiling box (G)through the cable cap (H), connect the power cable as shown in the (wiring diagram);

4. The ceiling box (G) is screwed through the I-bracket (F) and the lpendant is installed.


Note: The above operations have to be done by professional workers.

i-LUMINOSITY
LED LIGHTING FIXTURES

Date: _____
Project: _____
Price: _____



Cable Connection



Installation manual for horizontal hanging

1.Fixed A in to the ceiling , Fixed B on A;
2.Fixed C into D , adjust the height after hanging E;
3.Fixed F on the ceiling ,fixed the wire on G by H , connected the AC wire according to the cable connection ;
4.Fixed G by F with screws , finished .
Note:All procedure have to been done by electrician.