





**i-LUMINOSITY**  
LED LIGHTING FIXTURES

Date:	_____
Project:	_____
Price:	_____

## 360 Degree Illumination Light Install Instructions



**Wiring  
diagram**



### Installation Instructions

- 1.** Fix the ceiling copper parts (A) on the ceiling, and screw the steel wires through the copper nuts (B) into the (A), then suspended them in turn;
- 2.** The telescopic copper piece (C) is screwed into the copper nut (D) to suspended the pendant. The height of the pendant could be 8' adjusted by (C);
- 3.** Fix the I-bracket (F) on the ceiling, and fasten the cable to the ceiling box (G) through the cable cap (H), connect the power cable as shown in the (wiring diagram);
- 4.** The ceiling box (G) is screwed through the I-bracket (F) and the pendant is installed.


Note: The above operations have to be done by professional workers.




**i-LUMINOSITY**

LED LIGHTING FIXTURES

Date:	_____
Project:	_____
Price:	_____



Cable Connection



## Installation manual for horizontal hanging

- 1.Fixed A in to the ceiling , Fixed B on A;
- 2.Fixed C into D , adjust the height after hanging E;
- 3.Fixed F on the ceiling ,fixed the wire on G by H , connected the AC wire according to the cable connection ;
- 4.Fixed G by F with screws , finished .

Note:All procedure have to been done by electrician.